



US


UNITED STATES

Diagram / Parts List

JR3070CTHZ

RECIPRO SAW





US	UNITED STATES
-----------	----------------------

JR3070CTHZ / RECIPRO SAW

Item	Sub	Parts No.	Parts Description	Qty	I/C	E/C No.	Close No.	Remark
001-1		163451-9	Shoe	1				
002		421904-7	Insulation cover	1				
003-1		424147-0	Protector	1				
004-2		257430-8	Retaining ring (EXT) 18	1				
005-2		310285-3	Driving sleeve	1				
006		268094-3	Pin 3	1				
007-2		327043-0	Guide sleeve	1				
008		417791-0	Driving sleeve guide	1				
009		418311-3	Sleeve	1				
010		345214-7	Push plate	1				
011		233025-1	Compression spring 2	1				
012		231687-9	Torsion spring 17	1				
013		257742-9	Shoulder sleeve 14	1				
014		213174-0	X-ring 14	1				
015		911225-0	Pan head screw M5X16 WM	4				
016		418806-6	Cap	1				
017		961012-7	Stop ring (EXT) E-6	1				
018		154551-6	Gear housing cover complete	1				
019		961012-7	Stop ring (EXT) E-6	1				
020		154502-9	Slider support complete	1				
021		233038-2	Compression spring 5	2				
022		423343-7	Seal plate 14	1				
023		214170-1	Plane bearing 14A	1				
024-3		168410-8	Slider	1				
025		345487-2	Slide plate	1				
026		317842-8	Gear housing	1				
027-1		154547-7	Bearing complete	1				
028		345486-4	Plate B	1				
029-1		911225-0	Pan head screw M5X16 WM	2				
030		265530-0	Hex. socket head bolt M5X8	3				
032		911225-0	Pan head screw M5X16 WM	3				
033		317844-4	Bearing box	1				
034-1		210340-0	Ball bearing 6001LLB	1				
036		213726-7	O-ring 62	1				
037		143569-2	Torque limiter complete	1				
038-1		266373-3	Binding head tapping screw 5X35	4				
039-1		265165-7	Hexalobular socket countersunk h- ...	1				
040		345479-1	Shoe guide	1				
041		232222-6	Leaf spring B	1				
042-1		911225-0	Pan head screw M5X16 WM	2				
043		345485-6	Plate A	1				
044		265531-8	Hex. socket head bolt M6X14	1				
045-1		154545-1	Crank cam complete	1				
046		257265-7	Ring 21	1				
047		313121-2	Counter weight	1				
048		154546-9	Crank base complete	1				
049		345489-8	Guide plate	1				
050-1		210339-5	Chain RS35-126	1				
051		265148-7	Hexalobular socket countersunk h- ...	4				
052		212957-5	Needle bearing 710	1				
054		418991-5	Stopper	1				
055		231309-1	Compression spring 5	1				
056		272247-8	Lever 20	1				
057		213021-5	O-ring 5	1				
058		213021-5	O-ring 5	1				
059		413095-8	Plate C	1				
060		421899-4	Seal ring	1				
061		268012-1	Flat fillister HD. pin 7	1				
062		162236-0	Shift button	1				
063		232221-8	Leaf spring A	1				
064		256158-5	Pin 3	1				
065		233345-3	Compression spring 6	1				
066		256492-3	Shoulder pin 5	1				
067		961052-5	Retaining ring (EXT) S-12	1				
068		253744-3	Flat washer 12	1				
				Interchange O : Yes X : No < : the new part can be substituted for the current. > : the current part can be substituted for the new. S : Interchangeable as a set.				

US	UNITED STATES
----	---------------

JR3070CTHZ / RECIPRO SAW

[illegible]