



Model WT04Z Parts List

A = Standard Equipment

O = Circuit Diagram

| Item# | Part# | Description | Q'ty Unit |
|-------|--------------|--------------------------|-----------|
| 001 | 183J75-5 | HOUSING SET | 1 PC. |
| | C10 252126-6 | HEX. LOCKING NUT M4-7 | 2 PC. |
| | D10 | INC. 27 | |
| 002 | 855H71-8 | WT04 NAME PLATE | 1 PC. |
| 003 | 266429-2 | TAPPING SCREW 3X16 | 8 PC. |
| 004 | 456039-5 | F/R CHANGE LEVER | 1 PC. |
| 005 | 632M06-4 | SWITCH UNIT | 1 PC. |
| 006 | 422228-4 | BUMPER | 1 PC. |
| 007 | 140B03-5 | HAMMER CASE COMPLETE | 1 PC. |
| | C10 213166-9 | O RING 12.5 | 1 PC. |
| 008 | 261140-1 | NYLON WASHER 20 | 1 PC. |
| 009 | 259065-1 | RING SPRING 5 | 1 PC. |
| 010 | 213014-2 | O RING 3 | 1 PC. |
| 011 | 327236-9 | HAMMER | 1 PC. |
| 012 | 216019-1 | STEEL BALL 3 | 24 PC. |
| 013 | 267380-9 | FLAT WASHER 20 | 1 PC. |
| 014 | 234064-4 | COMPRESSION SPRING 21 | 1 PC. |
| 015 | 267813-4 | WASHER 21 | 1 PC. |
| 016 | 216002-8 | STEEL BALL 4.8 | 2 PC. |
| 017 | 226190-3 | SPUR GEAR 18 | 2 PC. |
| 018 | 327127-4 | SPINDLE | 1 PC. |
| 019 | 268217-3 | PIN 3.5 | 2 PC. |
| 020 | 253052-2 | FLAT WASHER 12 | 1 PC. |
| 021 | 226191-1 | INTERNAL GEAR 45 | 1 PC. |
| 022 | 140B04-3 | BEARING BOX COMPLETE | 1 PC. |
| | C10 213188-9 | O-RING 13 | 1 PC. |
| 023 | 632L96-1 | MOTOR COMPLETE | 1 PC. |
| 024 | 422273-9 | CUSHION | 4 PC. |
| 025 | 644813-5 | TERMINAL | 1 PC. |
| 026 | 855H77-6 | WT04 SERIAL NO. LABEL | 1 PC. |
| 027 | 183J75-5 | HOUSING SET | 1 PC. |
| | C10 252126-6 | HEX. LOCKING NUT M4-7 | 2 PC. |
| | D10 | INC. 1 | |
| 028 | 817D86-9 | CAUTION LABEL | 1 PC. |
| 029 | 136038-0 | ANVIL ASS'Y | 1 |
| | D10 | INC. 9,10 | |
| A01 | 266622-8 | + TRUSS HEAD SCREW M4X12 | 1 PC. |
| A02 | 346909-5 | HOOK | 1 PC. |